UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 7,095,261 B2

Page 1 of 1

DATED

APPLICATION NO.: 10/840015 : August 22, 2006

INVENTOR(S)

: Adrian J. Drexler et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

TITLE page, (75) Inventors: change "Seong-hoon" to -- Seong-Hoon--.

TITLE page, (56) References Cited: In "6,556,489; 6,586,979; 6,727,734; 6,735,148; 6,737,897; 6,759,883; 6,774,687; 6,781,861; 6,803,826; 6,850,107" change "B1" to --B2--.

Column 3, line 38, change "tck" to --tck--.

Column 7, line 47, change "tck" to --tck--.

Claim 12, column 10, replace 22 lines of text from

"a second multiplexer" through "through the same number of delay elements."

Replace with:

-- In response to receiving an indication, means for continuing to generate said synchronized clock signal in response to said delayed fed back synchronized clock signal independent of said reference signal. --

Signed and Sealed this

Sixteenth Day of January, 2007

JON W. DUDAS Director of the United States Patent and Trademark Office